



Michael O. Leavitt Governor Dianne R. Nielson, Ph.D. Executive Director Don A. Ostler, P.E.



DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WATER QUALITY

288 North 1460 West P.O. Box 144870 Salt Lake City, Utah 84114-4870 (801) 538-6146 (801) 538-6016 Fax (801) 536-4414 T.D.D. www.deq.state.ut.us Web

April 16, 1998

Mr. Gary Gray, Engineer Genwal Resources, Inc. P.O. Box 1420 Huntington, Utah 84528

Dear Gary:

Subject:

Reconnaissance Inspection UT0024368

I had a chance to visit the Genwal Coal mine site newly constructed sedimentation pond. It appears sufficient to handle the runoff generated. I realize you were busy underground and I appreciate the opportunity to observe the pond.

A short inspection report is attached. If you have any questions, give me a call at 538-6058.

Sincerely,

Michael D. Herkimer, Environmental Scientist

Permits & Compliance Section

MDH: ja

Enclosure

cc: Donna Inman, EPA Region VIII (w/encl)

Claron Bjork, Southeast District Health Dept. (w/encl)

Dave Ariotti, District Engineer (w/encl)

DOGM, Utah Coal Regulatory Program (w/encl)

F:\WQ\PERMITS\MHERKIME\WP\GENWAL.LTR FILE: Water Quality Board Leroy H. Wullstein, Ph.D. Chairman Lynn F. Pett Vice Chairman

Robert G. Adams
R. Rex Ausburn, P.E.
Nan Bunker
Leonard Ferguson
Dianne R. Nielson, Ph.D.
K.C. Shaw, P.E.
Ronald C. Sims, Ph.D.

William R. Williams
Don A. Ostler, P.E.
Executive Secretary

J. Ann Wechsler

Form Approved United States Environmental Protection Agency OMB No. 2040-0003 Washington, D. C. 20460 Approval Expires 7-31-85 Section A: National Data System Coding Transaction Code **NPDES** Yr/Mo/Day Inspection Type Inspector Fac Type 3 <u>IUIT 10 10 12 14 13 16 18 1</u> 1 <u>[N]</u> 2 151 12 19 18 1 0 1 3 1 3 11 1 19 <u>| S |</u> 17 18 <u>IR I</u> 20 121 Remarks 66 Reserved **Facility Evaluation Rating** ві QA -----Reserved-----67 1 1 69 70 📙 71 <u>IN</u> 72 <u>INI</u> 73 | | 74 1111180 Section B: Facility Data Name and Location of Facility Inspected Entry Time Permit Effective Date GENWAL RESOURCES INC. P.M./4-31-98 CRANDELL CANYON UP HUNTINGTON CANYON Exit Time/Date Permit Expiration Date P.M./4-31-98 8/31/00 Name(s) of On-Site Representative(s) Title(s) Phone No(s) NO ONE MET THE INSPECTOR AT MINE AS THE ENVIRONMENTAL PEOPLE WERE BUSY UNDERGROUND Name, Address of Responsible Official Title GARY GRAY, ENGINEER PO BOX 1420 Phone No. Contacted **HUNTINGTON, UTAH 84528** 687-9813 Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated) Permit Flow Measurement Pretreatment Operations & Maintenance Records/Reports Laboratory Compliance Schedules Sludge Disposal Facility Site Review Effluent/Receiving Water Self-Monitoring Program Section D: Summary of Findings/Comments (Attach additional sheets if necessary) TRAVELED UP TO GENWAL COAL MINE SITE AND OBSERVED THE NEWLY INSTALLED SEDIMENTATION POND. IT APPEARS TO BE WELL CONSTRUCTED. Agency/Office/Telephone 420-88 MICHAEL D. HERKIMER DIVISION OF WATER QUALITY Signature of Reviewer DONALD A. HILDEN Sonces a Lellen Agency/Office DIVISION OF WATER QUALITY Regulatory Office Use Only Action Taken Date Compliance Status Noncompliance

Compliance